Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section Sheet: Property ID: Lot #: File #: Code:

## SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Matter 1	IER STSTEM		
Location of Site:	Property Recorded: ic Individual Well Pit Cut	Property Size:  Spring  Mixed	Other

P R O F	.1940 Landscape Position/ Slope %	Horizon Depth (In.)	SOIL MORPHOLOGY		OTHER PROFILE FACTORS				
L E #			.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
1	L	0-15	LS	fr	>42"	×12"	_	Rock 942	5.4
	L 2-5%	15-42	501	Fi					
2	,		1.6		10.28/1	>46		Rock.	5.4
2	2-5%	0-14	SCI	Fi	104R8/1 >40"	710		0 48	
3	1	0-19	15	F	>42"	>42"		Roca @ 42	5.4
,	L 2.5%	19-412	SII	Fi	,				
	4								
						2 "			
						N			

Description	Initial System	Repair System	Other Factors (.1946): Site Classification (.1948):
Available Space (.1945)	~	V	Evaluated By: MARE (tt /AT
System Type(s)		V	Others Present:
Site LTAR	. 4	. 4	

COMMENTS: \_\_\_\_

LANDSCAPE POSITIONS	GROUP	TEXTURES	. <u>1955 LTAR</u>	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE	I	S-SAND LS-LOAMY SAND	1.2 - 0.8	VFR-VERY FRIABLE FR-FRIABLE	NS-NON-STICKY SS-SLIGHTY STICKY
FS-FOOT SLOPE N-NOSE SLOPE H-HEAD SLOPE	П	SL-SANDY LOAM L-LOAM	0.8 - 0.6	FI-FIRM VFI-VERY FIRM EFI-EXTREMELY FIRM	S-STICKY VS-VERY STICKY NP-NON-PLASTIC
CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE	Ш	SI-SILT SIL-SILT LOAM CL-CLAY LOAM	0.6 - 0.3	EFEATREMENT FIRM	SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC
FP-FLOOD PLAN		SCL-SANDY CLAY LOAM			

IV SIC-SILTY CLAY 0.4 - 0.1 C-CLAY

SC-SANDY CLAY

STRUCTURE SG-SINGLE GRAIN M- MASSIVE CR-CRUMB GR-GRANULAR SBK-SUBANGULAR BLOCKY ABK-ANGULAR BLOCKY PL-PLATY

PR-PRISMATIC

MINERALOGY SLIGHTLY EXPANSIVE

**EXPANSIVE** 

Show profile locations and other site features (dimensions, references or benchmark, and North) 1 12