Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section Sheet:
Property ID:
Lot #:
File #:
Code:

SOIL/SITE EVALUATION							
for	ON-SITE	WASTEWATER SYSTEM					

R O F I L E	.1940 Landscape Position/ Slope %	Horizon Depth (In.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				
			.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
l	L	0-16	LS	Fr Fi	>48"	>48"		_	5.3
	L 2-5%	16-48	SCI	Fi					5
2	,	G 111	15	fr	>48''	>018"		_	5.3
<i>C</i>	2.5%	14-48	SCI	Fi	- 10		v		
3	1	6-14	15	Fe	>48"	>48"	_	_	5.3
,	2.5%	14-48	SCI	Fi Fi					
	290						*		
	(67						1 3		
	i s						1		
				,			*		
					# 8 ·		=		
	22.								
								2 1 1 1 1	

Description	Initial System	Repair System	Other Factors (.1946): Site Classification (.1948):
Available Space (.1945)			Site Classification (.1948): Evaluated By: REHS
System Type(s)		-	Others Present:
Site LTAR	. 3	. 3	

COMMENTS: ____

LANDSCAPE POSITIONS	GROUP	TEXTURES	. <u>1955 LTAR</u>	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE	Ι .	S-SAND LS-LOAMY SAND	1.2 - 0.8	VFR-VERY FRIABLE FR-FRIABLE	NS-NON-STICKY SS-SLIGHTY STICKY
FS-FOOT SLOPE	II	SL-SANDY LOAM	0.8 - 0.6	FI-FIRM	S-STICKY
N-NOSE SLOPE	- · · · · · · · · · · · · · · · · · · ·	L-LOAM		VFI-VERY FIRM	VS-VERY STICKY
H-HEAD SLOPE				EFI-EXTREMELY FIRM	NP-NON-PLASTIC
CC-CONCLAVE SLOPE	III	SI-SILT	0.6 - 0.3		SP-SLIGHTLY STICKY
CV-CONVEX SLOPE		SIL-SILT LOAM			P-PLASTIC
T-TERRACE		CL-CLAY LOAM			VP-VERY PLASTIC
FP-FLOOD PLAN		SCL-SANDY CLAY LOAM			

SIC-SILTY CLAY 0.4 - 0.1 IV C-CLAY

SC-SANDY CLAY

STRUCTURE SG-SINGLE GRAIN M- MASSIVE CR-CRUMB **GR-GRANULAR** SBK-SUBANGULAR BLOCKY ABK-ANGULAR BLOCKY PL-PLATY

MINERALOGY SLIGHTLY EXPANSIVE

EXPANSIVE

PR-PRISMATIC Show profile locations and other site features (dimensions, references or benchmark, and North) M 2 South River Rd