Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section Sheet:
Property ID:
Lot #:
File #:

Code:

## SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

P R O F I L E	.1940 Landscape Position/ Slope %	Horizon Depth (In.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				
			.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
1	L	0.70	LS	fr	>48"	>48"	_	_	5.6
	2-5%	20-48	SL	Fr	-				
Z,3	L	0-24	15	fr	>48"	>48*	_	_	5.6
	2-5%	24-48	Sl	fr					
	# 1								
					(#.				
	- 1	i.							
	T.								
					18			8 "	7
							Li		

Description	Initial System	Repair System	Other Factors (.1946): Site Classification (.1948):	5	
Available Space (.1945)	-		Evaluated By:	MAREH	
System Type(s)	4	1	Others Present:		
Site LTAR	.6	. 6			

COMMENTS: \_\_\_\_

LANDSCAPE POSITIONS	<u>GROUP</u>	TEXTURES	. <u>1955 LTAR</u>	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE	I	S-SAND LS-LOAMY SAND	1.2 - 0.8	VFR-VERY FRIABLE FR-FRIABLE	NS-NON-STICKY SS-SLIGHTY STICKY
FS-FOOT SLOPE N-NOSE SLOPE H-HEAD SLOPE	II	SL-SANDY LOAM L-LOAM	0.8 - 0.6	FI-FIRM VFI-VERY FIRM EFI-EXTREMELY FIRM	S-STICKY VS-VERY STICKY NP-NON-PLASTIC
CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	Ш	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3		SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC

IV SIC-SILTY CLAY C-CLAY

0.4 - 0.1

SC-SANDY CLAY

**STRUCTURE** SG-SINGLE GRAIN M- MASSIVE CR-CRUMB GR-GRANULAR SBK-SUBANGULAR BLOCKY ABK-ANGULAR BLOCKY PL-PLATY

MINERALOGY SLIGHTLY EXPANSIVE

EXPANSIVE

PR-PRISMATIC Show profile locations and other site features (dimensions, references or benchmark, and North) (1) 2

Dove Rd