Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section Sheet: Property ID: Lot #: File #: Code:

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Location of Site:	Date Evaluated: Design Flow (.1949): Property Recorded: C Individual Well Pit Cut age Industrial Process	Property Size: Spring Mixed	☐ Other
-------------------	---	-------------------------------	---------

.1940			SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				
I L E #	Landscape Position/ Slope %	Horizon Depth (In.)	.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
	1	0-32	W	Fr/NSPX	> 48"	> 48"	_	_	5.6
	2-5%	32-48	SL	Fr/sspx					
)	4	0-28	25	frluspx	> 48 "	>48	_	_	5.6
	2-59	28-48	SL	to/sspx					
	6	0-30	LS	Fr/NSPX	>41.	>48"		-	5.6
	5-72	30-48	SC	Folsopx Folsopx					
_									
_									
_									
							1,		
_			-	2 75/ 8					

Description	Initial System	Repair System	Other Factors (.1946): Site Classification (.1948):
Available Space (.1945)	-	V	Evaluated By: MARCH
System Type(s)	L		Others Present:
Site LTAR	.6	-6	

COMMENTS: ____

LANDSCAPE POSITIONS	GROUP	TEXTURES	.1955 LTAR	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE	I	S-SAND LS-LOAMY SAND	1.2 - 0.8	VFR-VERY FRIABLE FR-FRIABLE	NS-NON-STICKY SS-SLIGHTY STICKY
FS-FOOT SLOPE N-NOSE SLOPE H-HEAD SLOPE	п	SL-SANDY LOAM L-LOAM	0.8 - 0.6	FI-FIRM VFI-VERY FIRM EFI-EXTREMELY FIRM	S-STICKY VS-VERY STICKY NP-NON-PLASTIC
CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	Ш	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3		SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC

SIC-SILTY CLAY 0.4 - 0.1 IV C-CLAY

SC-SANDY CLAY

STRUCTURE SG-SINGLE GRAIN M- MASSIVE CR-CRUMB GR-GRANULAR SBK-SUBANGULAR BLOCKY ABK-ANGULAR BLOCKY PL-PLATY

MINERALOGY SLIGHTLY EXPANSIVE

EXPANSIVE

PR-PRISMATIC Show profile locations and other site features (dimensions, references or benchmark, and North) 1