Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section Sheet: Property ID: Lot #: File #:

Code:

## SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

IOI OIL DILL THIS LETTIN	The state of the s		
Owner: Chose Facas - Applicant: Address: 397 Cypess (Lach Proposed Facility: 5 F 0	Date Evaluated:	- 40	
Proposed Facility: '5F0	Design Flow (.1949): 480	Property Size:	
Location of Site:	Property Recorded:		
Water Supply:   ☑ Pub	lic Individual Well	☐ Spring	Other
Evaluation Method: Auger Boring	Pit [	Cut	
Type of Wastewater: Sev	vage Industrial Proces	ss Mixed	

	.1940	Horizon Depth (In.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				
E Posi	Landscape Position/ Slope %		.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
2	L	0-28	13	Folispx	>48"	>48"	_	_	5.6
	L 2-5%	28-48	SL	Folispx Folisspx					
							_		

Description	Initial	Repair System	Other Factors (.1946):
	System		Site Classification (.1948):
Available Space (.1945)	V	V	Evaluated By:
System Type(s)	<u></u>	V.	Others Present: A LEHS
Site LTAR	.6	. 6	100117

COMMENTS: \_\_\_\_

LANDSCAPE POSITIONS	<u>GROUP</u>	TEXTURES	. <u>1955 LTAR</u>	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE	I	S-SAND LS-LOAMY SAND	1.2 - 0.8	VFR-VERY FRIABLE FR-FRIABLE	NS-NON-STICKY SS-SLIGHTY STICKY
FS-FOOT SLOPE N-NOSE SLOPE H-HEAD SLOPE	II	SL-SANDY LOAM L-LOAM	0.8 - 0.6	FI-FIRM VFI-VERY FIRM EFI-EXTREMELY FIRM	S-STICKY VS-VERY STICKY NP-NON-PLASTIC
CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	III	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3		SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC

0.4 - 0.1

STRUCTURE
SG-SINGLE GRAIN
M- MASSIVE
CR-CRUMB
GR-GRANULAR
SBK-SUBANGULAR BLOCKY
ABK-ANGULAR BLOCKY
PL-PLATY

MINERALOGY SLIGHTLY EXPANSIVE

SIC-SILTY CLAY C-CLAY SC-SANDY CLAY

EXPANSIVE

IV

