Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section Sheet: Property ID: Lot #: File #:

Code:

## SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

P R O F I L E	.1940 Landscape Position/ Slope %	Horizon Depth (In.)	SOIL MORPHOLOGY		OTHER PROFILE FACTORS				
			.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
l	1	0-26	15	FFINSPX	-> c18	>18"	_	_	5-6
	5.78	26-418	SL	Fr/NSPX					
					#				
7	L	0-26	LS	Frluspx	> c18"	>48"	_	-	5.6
	L 5-72	16-48	SL	Folispx Folispx	ti.				
3	1	0-24	LS	Frhspx	>48"	>48^	_	-	5.6
	5-7%	24-48	SL	Fr/NSPX					
				8					
_									
1									

Description	Initial System	Repair System	Other Factors (.1946): Site Classification (.1948):
Available Space (.1945)	-	-	Evaluated By: MREH
System Type(s)	4	-	Others Present:
Site LTAR	.6	.6	TOURSON STATISTICS

COMMENTS: \_\_\_\_

LANDSCAPE POSITIONS	<b>GROUP</b>	TEXTURES	. <u>1955 LTAR</u>	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE	I	S-SAND LS-LOAMY SAND	1.2 - 0.8	VFR-VERY FRIABLE FR-FRIABLE	NS-NON-STICKY SS-SLIGHTY STICKY
FS-FOOT SLOPE N-NOSE SLOPE H-HEAD SLOPE	II	SL-SANDY LOAM L-LOAM	0.8 - 0.6	FI-FIRM VFI-VERY FIRM EFI-EXTREMELY FIRM	S-STICKY VS-VERY STICKY NP-NON-PLASTIC
CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	Ш	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3		SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC

STRUCTURE
SG-SINGLE GRAIN
M- MASSIVE
CR-CRUMB
GR-GRANULAR
SBK-SUBANGULAR BLOCKY
ABK-ANGULAR BLOCKY
PL-PLATY

MINERALOGY SLIGHTLY EXPANSIVE


SC-SANDY CLAY

SIC-SILTY CLAY 0.4 - 0.1

**EXPANSIVE** 

C-CLAY

IV



- Persimmen Tran ->