

# SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

APPLICANT NAME \_\_\_\_\_

DATE \_\_\_\_\_

FACTORS		PROFILES									
		1	2	3	4	5	6	7	8	9	10
LANDSCAPE POSITION	.1940	L	L	L							
SLOPE (%)	.1940	2	2	2							
HORIZON 1 DEPTH		0-18									
Texture Group	.1941(A)(1)	SL									
Consistence	.1941	FL									
Structure	.1941(A)(2)	GL									
Mineralogy	.1941(A)(3)	NSSP									
HORIZON 2 DEPTH		18-24									
Texture Group	.1941(A)(1)	SCL									
Consistence	.1941	FL									
Structure	.1941(A)(2)	GL									
Mineralogy	.1941(A)(3)	NSSP									
HORIZON 3 DEPTH		24-42									
Texture Group	.1941(A)(1)	SC-CL									
Consistence	.1941	SI FLW									
Structure	.1941(A)(2)	SBL									
Mineralogy	.1941(A)(3)	SSG									
HORIZON 4 DEPTH											
Texture Group	.1941(A)(1)										
Consistence	.1941										
Structure	.1941(A)(2)										
Mineralogy	.1941(A)(3)										
SOIL WETNESS	.1942	36	36	36							
RESTRICTIVE HORIZON	.1944										
SAPROLITE	.1943/1956										
CLASSIFICATION	.1948										
LONG TERM ACCEPTANCE RATE	.1955	.4	.4	.4							